

Meremere, New Zealand Power Station Closure and Rehabilitation

Client

Genesis Energy.

Project

Closure, partial demolition and rehabilitation of a former coal-fired power station for commercial use. Building rehabilitation included removal of asbestos, switchyard and conveyor belts and construction of stormwater systems to operate without pumping. A refuse landfill, asbestos disposal site and ash ponds were rehabilitated for agricultural use.

Services provided

- Options review
- Community consultation
- Site investigations
- Resource consent applications
- Expert witness testimony
- Stormwater design
- Landfill rehabilitation design
- Asbestos removal specification
- Tender and contract management
- Environmental monitoring
- Site management planning.



www.tonkin.co.nz

ENVIRONMENTAL AND ENGINEERING CONSULTANTS