



**Tonkin & Taylor**

Waiuku, New Zealand Diesel Spill Remediation

## Waiuku, New Zealand Diesel Spill Remediation

### Client

Chevron NZ Ltd.

### Project


A diesel spill from a service station underground storage tank impacted a shallow aquifer, discharging to surface in a park beside a childcare centre. Tonkin & Taylor provided emergency response services, tracing the source of the spill, installing emergency and then long term remedial systems, liaising with District and Regional Council staff.

### Services provided

- Emergency response surface cleanup
- Soil and groundwater investigations
- Health and safety advice
- Remedial system design and specification
- Remediation supervision.



[www.tonkin.co.nz](http://www.tonkin.co.nz)



**ENVIRONMENTAL AND ENGINEERING CONSULTANTS**